
















CPU Jumpers on Lanner Electronics AP-520

Industrial Motherboard. Tested with an AMD K62-400AFR in Dec of '23

<u>Front Side Bus</u>	<u>J4</u>	<u>Multiplier</u>	<u>J10</u>
50 Mhz		4.5x	
unknown (No POST)		2.5x	
83.5 Mhz		4.0x	
60 Mhz		6.0x	
unknown (No POST)		5.0x	
75 Mhz		3.0x	
68 Mhz		unknown (No POST)	
66 Mhz		3.5x	